STAFF REPORT CONCERNING APPLICATION FOR A CERTIFICATE OF APPROPRIATENESS

Date: August 9, 2018

Application Number:2018-0727Property Location:417 W Navarre AvenueArchitectural Style/Date/Architect or Builder:Queen Anne / 1919Property Owner:BAC Home Loans Servicing LPLandmark or District Designation:Chapin Park Local (Ordinance #9574-05) and National Historic DistrictRating:Outstanding

DESCRIPTION OF STRUCTURE/SITE: Three story Queen Anne (irregular plan) on a brick foundation. Two chimneys punctuate the roof line and have decorative vertical brick string course, polygonal appearance due to central pinching. The wood shingles decorate the exterior as well as the peaks on the second story, with clapboard elsewhere. Considerable decoration is on the west face of the second story. The roof is hipped with gables, barge board on the gables, and has a molded cornice. The south face has an enclosed brick porch with wall and pillars, stone sills, and double-hung sashes. The front entrance was formerly composed of wood double-leaf multi-paned doors with glass in upper quarter. Original screened French doors exist.

<u>ALTERATIONS</u>: Certificate of Appropriateness #2013-1202A allowed for the in-kind replacement of a 32" x 85" wood frame window. COA #2016-0218 allowed for the in-kind repair of rear exterior window stairs and repair wood siding, as well as the trimming of vegetation 18" from the structure. RME #2018-0517A allowed for the replacement of the roof. RME #2018-0725A allowed for the trimming of vegetation away from the fence, deck, and structure. The front door was discarded without COA and replaced with new steel French double doors with 15-lites each.

APPLICATION ITEMS: "All ready performed, installed front door."

DESCRIPTION OF PROPOSED PROJECT: Applicant seeks a *retroactive* Certificate of Appropriateness for changes on the structure:

1. The replacement of the wood double-leaf multi-paned front doors with a Jeld-Wen Steel Door, "DG Full-Lite w/ Ext Grid WF", model number JEL-M-2-03808-00001.

SITE VISIT REPORT: N/A

STANDARDS AND GUIDELINES: CHAPIN PARK

C. WINDOWS AND DOORS

Window and door frames are in most cases wood and vary depending upon the style of the home. Many are double-hung windows with wood trim and sills. Brick structures have stone sills and brick lintels. In some cases where aluminum siding has been applied, the window and door trim has been covered. About half of the structures in the district have aluminum storm windows; the other half have wood storm windows.

Required

Original windows and doors shall be retained including sashes, lintels, sills, shutters, decorative glass, pediments, hoods and hardware. When deteriorated beyond repair, they shall be replaced with units and trim resembling the original. Recommended

Wood storm windows and doors painted or finished to match the original should be used but should not damage existing frames. If new sashes or doors are installed, the existing or original materials, design and hardware should be used. When metal storm doors are used, they should be painted, anodized or coated to match the existing. When awnings are used, they should be of canvas material. **<u>STAFF RECOMMENDATION</u>**: Staff recommends denial of new steel door and recommends replacement with new wood door to resemble original. If retroactive approval is given, Staff recommends painting door to coincide with existing color scheme of house.

Prepared by Adam Toering Historic Preservation Specialist

Recommendation by Elicia Feasel Historic Preservation Administrator



Figure 1 – 417 W Navarre from the street, looking north. The subject door is behind the storm doors.



Figure 2 -- Close-up of the replacement doors on the front porch of the structure.



Figure 3 – Close-up of the manufacturer's label.



Figure 4 - View of the front door on September 26, 2017.

wood	wood
glass	glass
wood	wood

Figure 5 – Staff interpretation of original door (as depicted from above photograph)

JUL 27 2018 MA \$20.00 Rec. 765715



HISTORIC PRESERVATION COMMISSION

OF SOUTH BEND AND ST. JOSEPH COUNTY County—City Building, South Bend, IN 46601 http://www.southbendin.gov/government/department/community-investment Phone: 574/235.9371 Fax: 574/235.9021 Email: hpcsbsjc@southbendin.gov

A Certified Local Government of the National Park Service

Elicia Feasel, Historic Preservation Administrator

APPLICATION FOR A — CERTIFICATE OF APPROPRIATENESS

OFFICE USE ONLY>>>>>>DO NOT COMPLETE ANY ENTRIES CONTAINED IN THIS BOX	
Date Received: 7/27/2018 Application Number: 2618 _ 6727	
Past Reviews: YES (Date of Last Review) 219-1725A NO	
Staff Approval authorized by: Title:	
Historic Preservation Commission Review Date:	
Local Landmark Local Historic District (Name)	
National Landmark National Register District (Name)	
Certificate Of Appropriateness: Denied Tabled Sent To Committee Approved and issued:	
Address of Property for proposed work: <u>417 Navarre</u> South Bend, IN (Street Number—Street Name—City—Zip)	
Name of Property Owner(s): Phone #:	
Address of Property Owner(s):	
Name of Contractor(s): Initial Secure (Brandon) Phone #: 1-313-915-5785	
Contractor Company Name: Toition Secure	
Address of Contractor Company: <u>33079 Garfield Rel 872.73 Frister MI</u> 48026 (Street Number-Street Name-City-Zip)	
Current Use of Building: Vacant (Single Family—Multi-Family—Commercial—Government—Industrial—Vacant—etc.)	
Type of Building Construction:	
Proposed Work: (more than one Landscape New Replacement (not in-kind) Demolition	
Description of Proposed Work: All ready performed, installed front door	
Owner e-mail: and/or Contractor e-mail:	
5. 60	
X and/or X Image: Contractor Signature of Owner Signature of Contractor	

By signing this application I agree to abide by all local regulations related to project and to obtain a Building Department Permit, if applicable.

-APPLICATION REQUIREMENTS ARE LISTED ON REVERSE SIDE-

Anglin tid. Chiqua taria

Adam, Here's the info. of the applicant that filled out the COA.

Tim Griffith 1607 Regent St. Niles, ME 49120 269-479-5155 Fiber glass